

DETAILS OF CONTRACTS CONCLUDED DURING THE MONTH NOVEMBER, 2025													
1 TENDER NO.	2 ITEM/ NATURE OF WORK	3 MODE OF TENDER ENQUIRY	4 DATE OF PUBLICATION OF NIT	5 TYPE OF BIDDING (SINGLE/TWO BID SYSTEM)	6 LAST DATE OF RECEIPT OF TENDER	7 NOS. OF TENDER RECD.	8 NOS. AND NAMES OF PARTIES QUALIFIED AFTER TECHNICAL EVALUATION	9 NOS. AND NAMES OF PARTIES NOT QUALIFIED AFTER TECHNICAL EVALUATION	10 WHETHER CONTRACT AWARDED TO LOWEST TENDERER/ EVALUATED L1	11 CONTRACT NO. & DATE	12 NAME OF CONTRACTOR	13 VALUE OF CONTRACT (In Rs.)	14 JUSTIFICATION FOR AWARD OF CONTRACT ON SINGLE TENDER/WORK ORDER
1	Work Order for "Highly skilled Manpower to OEM Expert for rectification work of thrust bearing problem of Unit#3 on urgent basis for CPS-1".	Work Order	-	-	-	-	-	-	-	No. NH/CPS-1/PHMM/2025/132 Dated :28/11/2025	M/s KK Industries plot no. 41/52 Industrial area NIT Faridabad (HR)	119086.00	The maintenance work of Unit-3 was assigned to M/s. KK Industries, Faridabad. The tasks related to machine alignment, centering, etc., were also carried out by the same firm. The parameters obtained from the work can be used to control the thrust bearing temperature. The firm has employees who possess experienced employees for this type of work. Hence the work was awarded on nomination basis.
2	Work order for Repair of Bolt tensioner (Power Master make) Model no DT-M120X6GP along with seal kit and coupler at CPS-1 on urgent basis.	Work Order	-	-	-	-	-	-	-	No. NH/CPS-1/PHMM/2025/123 Dated :11/11/2025	M/s Power master Engineers Private Ltd., A-701-702 M.I.D.C Kharim Navi Mumbai 400705	76700.00	During Capital maintenance work of Unit #3 (started 08/10/2025) dismantling & repairing of parts like the DT cone, BDR, runner, etc. were required. To dismantle the runner, the runner's coupling bolt needed to be opened using a bolt tensioner (loosens bolt at a specified pressure). While opening the bolt, the bolt tensioner (purchased in 2012) carbon seal got damaged & punctured, making it impossible to loosen the runner bolt, which was hindering the maintenance work. The seal for the bolt tensioner was not available in the powerhouse. OEM, M/s Power Master Engineers Pvt. Ltd., Mumbai, confirmed the seal for this model is available only in limited quantity. Hence, purchase & replacement of the seal were necessary.
3	Work order for Repair of Power Team make Hydraulic jack model no C556C & RH 306 through authorized service dealer at CPS-1 on urgent basis.	Work Order	-	-	-	-	-	-	-	No. NH/CPS-1/PHMM/2025/126 DATE:18-11-2025	M/S Neotech Equipments Pvt. Ltd., C-106 2ND FLOOR phase-II industrial area Mayapuri Delhi-110064	58817.00	Due to the 2025 monsoon disaster, underwater parts of the machine suffered significant erosion, prompting capital maintenance of Unit 3 from October. Hydraulic jacks used for handling BDR, runner cone, runner, labyrinth, etc., became unusable because of seal leakage. The same jacks are needed for 2025-26 annual maintenance, hence they need to be repaired urgently. Since annual maintenance work will also be underway at other power stations during that period, it will not be possible to obtain jacks from those stations. The 55-ton and 30-ton capacity hydraulic jacks are manufactured by M/s Power Team, and considering the compatibility and fitment of the seals used in them, it is necessary to install only OEM seals. M/s Neotech Equipments Pvt. Ltd, Delhi, is the authorized dealer/service provider for the OEM, seals. Hence work awarded through nomination basis.

DGM (PFC)

Abhishek
SMC

Rinki (JE)