

**Details of consultants engaged/work/purchases awarded on Nomination Basis during the period 01.01.2025 to 31.03.25 (4th Qtr.)**

**Name of Project:** *Teesta Low Dam - IV Power Station*

Sl. No.	Supply/Work Order No. & Date	Description of work	Mode of tendering	Name of Contractor / Supplier	Award Amount (INR)	Details of circumstances for going for single tender. (CVC circular dt.05.07.2007	Justification for award of work/contract on single tender.	Use of website to bring transparency in award of contract.(CVC circular dt 11/02/2004)	Information regarding posting o details on award of tender /contracts on website.(CVC circular dtd. 14/07/2009)
1	GEMC-511687721771376 Dated:13.03.2025	Purchase of Signal Converters for Flow Sensor installed in Power House, TLD-IV PS	GeM	M/s KROHNE MARSHALL PVT LTD. PIMPRI, PUNE - 411018, MAHARASHTRA-	1003000.00	PAC Item	PAC Item	GeM	GeM
2	GEMC-511687716368643 Dated:03.01.2025	Purchase of Rubber Items for generating units. (FY 2024-25)	GeM	M/s INDIAN RUBBER PRODUCTS Haridwar	220645.84	PAC Item	PAC Item	GeM	GeM
3	NH/TLD-IV/HM/2024-25/2461 Dated 03.03.25	Deployment of Service Engineer for repair/replacement of VFD of Gantry Crane of TLD-IV PS	Work Order	M/s Vision Comptel Kolkata	53100/- including GST + 15012 Airfare	The procurement is possible from single source only	While starting to lift the third gate the hoist command not operated due to sudden failure of VFD . The maintenance team along with the engineers and electricians of PH have been engaged to sort out the problem. It has been found that the VFD of this crane is faulty which was replaced immediately with One piece of spare VFD 22 KW/ . However even that was not functioning hence the D?T gate was not raised from the groove. Therefore only 2 generating units are available out of 4. Another gantry crane could not be used because this is the last D/T gate beyond the rail extension.	NA	Complied
4	Work order no : NH/TLDP-IV/PS/Transport/2025/4683, dated 07/03/2025	R&M of Tata tipper No : WB-73E-9025	Work Order	OSL automobiles Pvt. Ltd.	18306	No	Authorized dealer	NA	Complied

OK

22-11-19

Sl. No.	Supply/Work Order No. & Date	Description of work	Mode of tendering	Name of Contractor / Supplier	Award Amount (INR)	Details of circumstances for going for single tender. (CVC) circular dt.05.07.2007	Justification for award of work/contract on single tender.	Use of website to bring transparency in award of contract.(CVC circular dt 11/02/2004)	Information regarding posting of details on award of tender /contracts on website.(CVC circular dtd. 14/07/2009)
5	NH/TLDP-IV/PH/2025/SC/Ca mp-Siliguri dt. 21.01.2025	Purchase of CRC India make electric equipment cleaner for stator winding, field winding, stator core, brush gear , rotor leads and DC connections	Purchase on PAC basis	M/s Ambica electricals Siliguri	35742	Contractor has exclusive rights in respect of the goods or services and no reasonable alternative or substitute exists	With time dirt and dust has been observed in stator winding , field winding , stator core , brush gear , rotor leads and Dc connections etc. M/s BHEL has mitioned procedures in O&M manual of generator to clean stator winding etc. . As per manual CRC lectra clean solvent is to be used for cleaning, in addition spray the treated surface with insulation assistance improving chemical CRC-2-26 O&M division has also recommended the same. Annual Maintanance of generating units are also going on, and the cleaning can be carried out in the same time hence it is proposed to purchase CRC India make Electric equipment cleaner (20L CRC lectra clean and 60 bottles CRC-2-26 ) for cleaning of remaining 3 units from OEM/authorised service provider.	Complied	Complied
6	NH/TLDP-IV /E&M /2024/LOA/22 dt. 08.03.2025	Deputation of service engineer for inspection of water tender vehicle WB 73E-0354 deployed at PS	Work Order	M/s Hindusthan technologies PVT. Ltd. Cuttack	18054	Contractor has exclusive rights in respect of the goods or services and no reasonable alternative or substitute exists	There is urgent requirement of overhauling /servicing of pump system and other equipments of water tender as a pump, monitor etc. are not working properly . Overhauling are utmost necessary thus it has been decided to repair and rectify water tende from OEM i.e. M/s Hindusthan technologies Pvt Ltd. Cuttack	NA	Complied
7	NH/TLDP-IV PS/E&M/WO/2025 /2103 dt. 19.02.2025	Conducting diagnostic tests on electrical equipment at TLD-IV PS	Work Order	M/s Central Power research Institute , Bengaluru	4905850	Contractor has exclusive rights in respect of the goods or services and no reasonable alternative or substitute exists mentioned in vigilance circular no. 07/2015-16 dt. 21.10.2015	Consider the high cost and ever growing demand for reliable power condition assessment of important HV/EHV electrical equipment like CT, CVT, LA etc. is very much required. To asses the condition diagonistic tests are decided to be conducted on electrical equipment from M/s Central Power Research Institute Bengaluru	NA	Complied

Sl. No.	Supply/Work Order No. & Date	Description of work	Mode of tendering	Name of Contractor / Supplier	Award Amount (INR)	Details of circumstances for going for single tender. (CVC) circular dt.05.07.2007	Justification for award of work/ contract on single tender.	Use of website to bring transparency in award of contract.(CVC circular dt. 11/02/2004)	Information regarding posting of details on award of tender /contracts on website.(CVC circular dtd. 14/07/2009)
8	NH/TLD-IV PS/PH(Civil) /2025 /408 dt. 05-02-2025/408 dated 05-02-2025	Removal of mud/silt from drainage sump and dewatering sump at PH of TLD-IV , Kalijhora	Work Order	M/s Ghanashyam Chetri	315933	Work is urgent and could not be avoided /awaited for award thru open tender as work has to be completed during lean period	Since monsoon is about to end water seepage to drainage sump is minimal hence working inside sump would be possible in case of any problem in the dewatering pumps or NRVs then it will be very difficult to rectify due to presense of silt/mud at the bottom of sump. It is very much necessary to clear this silt/mud urgently	NA	Complied
9	NH/TLD-IV PS/ Dam Civil/2025/09 dt 06/01/25	Repair of frost aluminium partition wall of intake power pack rooms at dam top, TLD-IV Kalijhora	Work Order	Shree Krishna Construction & service, Kalijhora bazar, Distt Darjiling	217469	Work is urgent in nature and could not be avoided /awaited for award through open tender as work has to be completed during lean season	Due to blockage of Siliguri Gangtok road traffic is moving through Dam/spillway due to which entry of large amt of dust is affecting all equipments installed in power pack room,. If the equipment stops, it may hamper the energy production. Hydro mechanical is being asked to get the power pack room repaired at the earliest, since work is very urgent and time bound it cannot be done through open tender, therefore in view of the agency it will be necessary to carry out the repair work very quickly through a work order.	NA	Complied

MGR/SM/GSM

AM/DM