Dec. 2023.

|   | DETAILS OF CONTRACTS CONCLUDED DURING THE MONTH 201 2023 |                            |   |                                |                         |  |   |   |   |   |                            |   |
|---|--|----------------------------|---|--------------------------------|-------------------------|--|---|---|---|---|----------------------------|---|
|   |  |                            | -   | -                              | 7                       | 8  | 9   | 10  | 11  | 12  | 13                         | 14  |
| 2<br>ITEM/ NATURE OF WORK   | 3<br>MODE OF TENDER<br>ENQUIRY                           | DATE OF PUBLICATION OF NIT | TYPE OF BIDDING<br>(SINGLE/TWO BID<br>SYSTEM) | LAST DATE OF RECEIPT OF TENDER | NOS. OF TENDER<br>RECD. | NOS. AND NAMES OF<br>PARTIES QUALIFIED AFTER<br>TECHNICAL EVALUATION | NOS. AND NAMES OF<br>PARTIES NOT QUALIFIED<br>AFTER TECHNICAL<br>EVALUATION | WHETHER CONTRACT<br>AWARDED TO LOWEST<br>TENDERER/ EVALUATED L1 | CONTRACT NO. & DATE   | NAME OF CONTRACTOR                              | VALUE OF CONTRACT (In Rs.) | SCHEDULED DATE OF COMPLETION OF SUPPLIES  |
|   | × "  |                            |   |                                |                         |  |   |   |   |   |                            | V =   |
| Supply, installation of windshield glasses of Caterpillar wheel loader                | Work order   |                            | 2   | *                              | 12-                     | 8°   |   | F 0   |   |   | =                          | Windshield glass of wheel loader was damaged due to landslide at site. The equipment is covered under mega insurance policy. Power station has submitted  |
|   |  | = .                        |   |                                |                         |  | 8   |   | NH/CPS-1/Workshop/WO/2023-<br>24/273-77 dated 01.12.23        | M/s Gainwell<br>Commosales Pvt. Ltd,<br>Mohalli | 3,44,907                   | information of damage to insurance company. Insurance company has surveyed the damages. The said equipment is deployed for road clearing work and othe earth work and is essential for Power station. Without                                     |
| g e   |  | , .                        | 107 (8  |                                |                         |  |   |   | Ę   |   | F                          | wind shield glass, the equipment cannot be deployed. Therefore Work order has been issued to authorised dealer of OEM. Delivery time-45 days  |
|   |  |                            |   |                                |                         |  |   | 8   |   |   | 8                          |   |
| Physical inspection and condition monitoring test for generators and transformers etc | Work order   |                            | V*  |                                |                         |  |   | 48<br>80  | NH/CPS-1/PH/2023-24/198/<br>dated 8.12.23                     | CPRI, Bengaluru                                 | 20,60,787                  | To check healthiness of generators, transformers etc, condition monitoring test are essentail/ CPRI is permier central govt. Institute for condition monitoring test Work is to be executed during annual maintenance 2023-24.                    |
| transformers etc  |  | * 6 * *                    |   |                                |                         | = =  | * 1   |   |   |   |                            |   |
|   |  |                            |   |                                |                         | 5  |   | 0 %   |   |   | (8)                        | *   |
| Cleaning of stator & rotor of generator during annual maintenance 2023–24             | Work order   | 2                          | 7 TE  |                                | ÷                       |  | E .   | 1.0   |   |   |                            | Considering guidelines issued by Design (E&M) and CPF   |
|   |  |                            | 41  |                                | 2 × ×                   | 2 de 2   | e x   | 120   | NH/CPS-1/PH/EMG-<br>97077/2023-24/203 dated M/<br>14.12.23    | M/s Sanjeet Roy                                 | 3,10,614                   | cleaning work of stator winding needs to be executed during annual maintenance peroid. For timely execution of work during annual maintenance 2023-24 and to save PAF/Generation loss, work on nomination basis have a warded. Completion-30 days |
|   | (E)  |                            |   | 2                              | 3                       |  |   |   |   |   |                            | , i   |
| Epoxy painting of underwater parts of generating units                                | Work order   | ă e                        |   | *                              |                         |  |   | - w-  | NH/CPS-1/PH-MMG/E-  |   |                            | After opening of spiral casing and draft tube cone, it is observed that epoxy painting of spiral casing area/draf tube area etc got damaged. To avoid further damage in   |
| 2<br>18   | 2  |                            | 8   |                                | 25                      |  | W1  | -   | 109780/WO-01/2023-24/212<br>dated 24.12.23                    | M/s Man Singh                                   |                            | underwater parts and to save genaration/PAF loss, work is awarded on nomination basis.  |
|   |  |                            |   | 8 8 8                          |                         |  |   |   |   |   |                            |   |
| AMC of elevator at Dam and<br>Power House   | Work order   |                            |   |                                | 37                      |  |   |   | NH/CPS-I/Dam<br>Elec/AMC/Elevator-2023/1349<br>dated 30.12.23 | M/s Omega Elevators                             | 6,73,001                   | Elevator is designed and installed by M/s Omega<br>Elevators. It has been mandated by lift inspector &<br>Executive Engineer, PWD-HP that routine and<br>preventative maintenace of lift should be done by OEN                                    |

→ DGM(PEC)

mudaan )