

Name of Power station/Complex:- Chamera - III Power Station Dharwala,Distt Chamba (H.P)

Detail of Consultants engaged/ work/ Purchases awarded on Nomination Basis Report (October -December 2025)

Sl.No.	Order No. & date	Description of work	Mode of Tendering	Name of Supplier/ Contractor	Awarded Amount (INR)	Details circumstances for going for single tender (CVC circular Dtd 05.07.2005)	Justification for award of contract on single tender	Use of Website to bring Transparency in Award of Contract (CVC Circular Dtd 11.02.2004)	Information Regarding Posting of Details on Award of tender/Contracts on website (CVC Circular Dtd 14.07.2009)	Sub contract No/ PO No.	
1	GEMC-511687757273165 dated 27-11-2025	Annual Maintenance Contract for Instrumentation Equipment at Chamera -III Power Station	Single tender (PAC)	M/s Encardio Rite Electronics Pvt. Ltd., A-7, Talkatora Industrial Estate, Talkatora Road, Lucknow, UP-226011	575840	The procurement is possible from single source only.	OEM	Yes	Complied	117/002337	Single Source
2	GEMC-511687749847173 dated 05-12-2025	Annual Maintenance Contract for Two DG Sets of 725 KVA each of Power House, Chamera -III Power Station	Single tender (PAC)	M/s GAINWELL COMMOSALES Pvt. Ltd., Unit No. 705, 7th Floor Godrej Waterside Tower-2, salt Lake City Sector-V, Kolkata WB-700091	566400	The procurement is possible from single source only.	OEM	Yes	Complied	117/002323	Single Source
3	NH/CPS-III/PH(E&M)/DGM(E)/2025-26/722 Dated: 11/10/2025	Replacement & repairing of Shaft seal wearing rings & repairing of balancing pipes of Unit#1, Chamera-III Power station, Dharwala, H.P.	Work Order	M/s Wave Hydro,Salooni, Distt-Chamba, HP.	281666.00	As per Vigilance Circular No. 06/2012-13 dated 31.12.2012 regarding award of contracts on nomination basis under exceptional circumstances, the contract can be awarded "where the supplier has exclusive rights in respect of the goods or services and no reasonable alternative or substitute exists", which is applicable in the present case also.	On 21/08/25 it has been observed that TGB temp are lowering and TGB vibration increasing. On inspection it's found that water has ingress in TGB oil sump of Unit 1 and its shaft seal wearing rings has wear out due to which shaft seal system is not functioning properly leading to ingress of water in TGB sump and vibration of TGB Shell increases above the permissible value. Operation of Unit with increased vibration is detrimental for Unit, and can have cascading damaging effect on other critical components and parameters of Unit. Unit can't be run with this condition. keeping in view the ongoing peak monsoon season and to avoid huge loss of generation & PAF it was decided to get the shaft seal replaced & repaired on urgency basis from outside agency having past experience in similar nature work. After taking necessary approval from competent authority work was awarded to M/s Power Electro Mechanics Pvt. Ltd., Chamba, HP	Yes	Complied	117/002310	Other
4	NH/CPS-III PS/W&T/24-25/25 dt 04.11.2025	Repair of Crain HP 73-3329	Work Order	M/s Shivam Automobile, Bilaspur, HP	280393.96	Repair of Crain	Repair of Crain from OEM	Yes	Complied		Other
5	NH/CPS-III/TS/Sofa Seat Repair /Job Order/2025/122 दिनांक: 14.10.2025	Repair work of sofa seat and dining chair by replacement of their cover fabric cushion and PU polishing along with replacement of back and front part of wooden Double Bed and polish work of wooden Double Bed of Chamera-III Power Station.	Work Order	M/s Dhiman Furniture House, Karian, Distt.-Chamba(H.P.)	Rs 6,63,396.00	The procurement is possible from single source only.	Keeping in view the nature, requirement and importance of the work,	Yes	Complied	117/002311	Other